

A C Howell Corp.
P.O. BOX 143
Howells, NY 10932
845-386-1900
845-267-7019

INVOICE

May 19, 2026

Anthony Coppola
8 Borden Street
Otisville, NY 10963

Account #:	9091
Invoice #:	105252
Transaction Date:	5/14/26
Total Due:	\$1,501.61

TERMS: Net Due in 15 Days.

Amount Enclosed: \$ _____

Please Return This Portion With Your Payment

Problems / Actions Performed:

INSTALLATION - HW Heater

Description: install 40 gallon bradford white water heater- remove old water heater= check for leaks, no leaks found

Quantity	Description	Unit Price	Amount
1.0	Installation - Labor	\$200.00	\$200.00
1.0	40 gal. bradford white water heater	\$1,125.00	\$1,125.00
1.0	Leak Test	\$0.00	\$0.00

Sub Total: \$1,325.00

Tax Total: \$107.66

You can now pay your bill online at www.achowell.com

Invoice Total: \$1,432.66

Prev. Balance: \$68.95

USD Total Due: \$1,501.61

Pay within 5 days of delivery- cash or check- receive \$0.10 off p/gal. credit reflected on next delivery

For Fuel or Service At: Anthony Coppola
8 Borden St
Otisville, NY 10963

A C Howell Corp.
P.O. BOX 143
Howells, NY 10932
845-386-1900

Account #: 9091
Invoice #: 105252
Transaction Date: 5/14/26

GAS APPLIANCE SYSTEM CHECK

5/26

Account Number 9091
Name Anthony Coppola
Address 8 Borden St Olatheville NY 10963

Company/Location A.C. Howell Corp.
Call Date _____ Date Requested _____
Call Taker Name _____

Telephone: Office _____ Home _____

Instructions _____

Performance Check: Item	Central Heating 1	Space Heater 2	Water Heater 3	Range 4	Clothes Dryer 5	6	
Manufacturer	oil	Belletts	Brands white				
Model No.			RB240S6X				
Serial No.			BF55341919				
Fuel			propane				
Manual Shutoff (Installed/Existing)			Inst				
Sediment Trap (Installed/Existing)			Inst				
Control Mfgr./Model No.			honeywell				
Pilot(s)/Pilot Safety System			OK				
Ignition Systems(s) Mfgr./Model No.			-				
Thermostats Mfgr./Model No.			-				
Burner(s)/Combustion Chamber			OK				
Venting System/Draft Diverter			OK				
Combustion Air			OK				
Red Tag (Removed from Service)/Recall			N/A				

Manufacturer TANK/CYLINDER (Additional Serial No.'s):

SIZE	SERIAL NUMBER	MFR.	MFR. DATE	LAST TEST DATE	LOCATION	TANK COND.	PAINT COND.	PIGTAIL COND.	FITTINGS COND.	GAUGE COND.	RELIEF VALVE			FITTINGS LEAK TEST
											COND.	DATE	CAP	
50 Gall	740122	Manchester	2015	N/A	W	OK	OK	OK	OK	OK	OK	15	✓	✓

PIPING/REGULATOR OPERATION/CONDITION

FITTINGS LEAK TEST	PIPING		REGULATOR MFR. DATE (CODE)	MFR.	REGULATOR CONDITION	MODEL	REG. VENT POSITION	HOW PROTECTED	FLOW PRESSURE	LOCK UP LEAK TEST
	MATERIAL	SIZE								
	Loose	1/2	13 Mar 21	MEL	good	MELPDDHBF	harza.	dome	11 IN WC	13 IN WC
TWO STAGE	1st								PSIG	PSIG
	2nd								IN WC	IN WC

SYSTEM LEAK TEST

SINGLE STAGE/ INTEGRAL/ SECOND STAGE	START PRESSURE (INCHES WC)	END PRESSURE (INCHES WC)	TIME HELD	SYSTEM OK
	50 PSIG	50 PSIG	5 mins	✓
TWO STAGE	1st			
	2nd			

This inspection covers propane/LP-gas items and equipment visible and accessible to the service technician and represents the conditions existing on the date of inspection. It does not cover latent or manufacturing defects, the internal working of sealed equipment, or structural components, and cannot be construed to cover future or unforeseen happenings.

I, _____
(Please Print)

- Know how to turn off gas in case of emergency.
- Have smelled propane and can detect its odor.
- Have received the Consumer Safety information and material.
- Had gas system deficiencies and/or corrections, if any, clearly explained to me.
- Am satisfied with the service work performed.

[Signature]
(Customer Signature)

Comments Install new water heater - no leaks found

Reference Invoice No. 2865 Date 5-14-26

I, _____
(Please Print)

Certify that I have completed the System Check as prescribed.

Performed Odor Test ☒ Yes

Performed Leak/Pressure Test

☒ Yes

Placed Safety Decal ☒ Yes

Left Consumer Safety Info and Material

☒ Yes

[Signature]

(Service Technician's Signature)